


PNEUMATIC Drive

For simplifying
mechanism designs

A pneumatic
drive-type sensor is
now on the market.

The pneumatic drive method
reduces mechanism design
processes significantly to
provide the ultimate system.

Using the pneumatic spindle
operation simplifies the
mechanism design
management to help reduce costs.
The reliable W-bearing structure
ensures excellent durability, allowing the sensor
to be used in a variety of environments.



When mounted with nuts

Hose clamp
included

Pneumatic drive control available



Switching air ON/OFF moves
the spindle up/down to make
line control for each process
easy.

- Portable terminal parts
- Camera parts
- Electronic components
- Automatic component inspection line
- Assembly

SA-S110PD/S510PD Specifications

Model	SA-S110PD	SA-S510PD
Position detection method	Optical absolute linear encoder method	
Measuring range	10 mm	
Resolution	0.1 μ m	0.5 μ m
Indication accuracy (P-P) *1	1.0 μ m or less	2.0 μ m or less
Measuring force	1.5 to 3 N *2	
Fluid used	Air	
Operating pressure range	0.10 to 0.12 MPa *3	
Air tube specification	Outer diameter: 4 mm / Inner diameter: 2.5 mm	
Withstand pressure	0.2 MPa	
Ingress protection rating *4	Equivalent to IP67	
Mass	Approx. 80 g	
Operating temperature/ humidity range	-10 to 55°C / 35 to 80%RH (with no condensation or icing)	
Storage temperature/ humidity range	-20 to 60°C / 35 to 80%RH	
Vibration resistance	10 to 500 Hz Double amplitude 3 mm (max 20 G) / 2 hours for each of the XYZ directions	
Impact resistance	1,960 mm/sec ² (200 G)	
Grounding method	Capacitor grounding	
Cable *5	Sold separately as an option	
Measuring probe	Ceramic sphere with a diameter of 3.175 mm	

*1: At an ambient temperature of 20°C.

*2: The measuring force varies depending on the air pressure used.

Removing the seal cap allows the use of this sensor as a low-measurement force type.
Refer to the manual that accompanies the product for the measuring force when the spindle is
pushed in with each position, and for the relationship between the supply air pressure without the
seal cap and the measuring force (in the right position).
In addition, the measuring force depends on the product assembling accuracy and how worn the
sealing material is (O-ring).

*3: When the seal cap is removed, the operating pressure range is 0.03 to 0.12 MPa.

*4: This applies only when it is in the right position, the air tube is connected, and the sealing part is not
degraded or damaged. The ingress protection rating does not apply when the seal cap is removed.

*5: An angle-type connector cable cannot be used.

⊗ This type is not fitted with rubber bellows.

* CITIZEN is a registered trademark of Citizen Watch Co., Ltd. * The information contained in this catalog is subject to change without prior notice.
* Colors shown in the photos may differ from the actual colors of products due to printing conditions.

Distributor:

Netherlands:
Hogetex / Kometex BV
Gesinkkampstraat 1
7051 HR Varsseveld
+31 (0)315-617171
www.hogetex.com

Germany :
Hogetex Deutschland GmbH
Am Hahnenbusch 14B
55268 Nieder-olm
+49 (0)6136-7628-0
www.hogetex.de

Belgium:
Hogetex Belgie BvBA
Kapelweg 132
2300 turnhout
+32 (0)14-703-404
www.hogetex.be